

EF25-033 PLAY AREAS

(i) **Normandy Common Repairs**

The zip line platform at Normandy Common had become rotten and dangerous. The maintenance team have fixed the platform with a new bit of wood and have glued the existing matting back onto the new wood.

The cost to replace the parts and labour was £550.