

EF25-057

PLAY AREAS

Normandy Common

The wood traversing wall at Normandy common had water damage through out and there were sharp areas along the top of the wall. The equipment was inspected and removed due to it becoming unsafe.

Proposal

To replace traversing wall, build a frame, installation, and labour.

Wall Replacement **£1,040.00+ VAT – Total £1,265**

Timber frame and fixings **£200 (approx.)**

Labour (maintenance team) **£300**

Total £1,540

Matters for consideration

Do the committee accept the proposal?

Zipline seat – the seat on the zipline is degrading and needs replacing. The seat is made by Sutcliffe play and the costs to replace the seat would be **£87.00 +VAT**

Total £102.00

Matters for consideration

Do the committee accept the proposal?

MFF rope spinner

The caps from some of the bolts have sheared off and need to be replaced. The Assistant Clerk has been in touch with Kompan to find out if this is covered within warranty and is awaiting a response.